


Highway 71/72 Refinery Site
Bossier City, Louisiana
Lead Removal Action
Fall/Winter 1996



Photograph #1 - Removal area #13 - buried, abandoned pipe (6 inch diameter) was uncovered during excavation.



Photograph #2 - This photo shows a portion of removal area 10. The black material in the excavated area is a coke-like material that was been wetted. A broken water pipe from excavation activities caused the wet conditions.



Photograph #3 - Removal area #3 - Black, coke-like material observed in this excavation.



Photograph #4 - This photograph shows part of removal area B. In the foreground, a member of the survey crew is measuring the removal depth. In the background, a track-hoe is loading contaminated soil into a haul truck for transportation to an approved landfill.



Photograph #5 - This photo shows part of removal area C, near the intersection of Old Minden Road and Interstate 20. Excavation continued down the embankment removing much of the surficial coke material.